

Feeding Screw Stages

Feeding Screw Model No. Description

PS 1 R C – 13

Model	Knob Type	Lock Type	Stroke / Guiding [mm]	Code 《Travel》
P: Precision S: Screw	1 : Pattern 2 : Hexagon Socket	M : Thread Type R : Cylinder Type	N : General Type / 1 C : Standard Type / 0.5	07 《7》 13 《13》 25 《25》

Feeding Screw Selection Table

GMT	Travel Stroke Range	Accuracy	Minimum Reading	Knob Type		Page
Model	mm	mm	Vernier	Pattern	Hexagon Socket	
PS1R □ -	0.7	0 ~ 7	0.03	●		P0329
	1.3	0 ~ 13				
	2.5	0 ~ 25				
PS2R □ -	0.7	0 ~ 7			●	P0329 } P0330
	1.3	0 ~ 13			●	
	2.5	0 ~ 25			●	
PS1M □ -	0.7	0 ~ 7		●		P0331
	1.3	0 ~ 13		●		
	2.5	0 ~ 25		●		
PS2M □ -	0.7	0 ~ 7	0.1 mm / Vernier		●	P0331
	1.3	0 ~ 13			●	
	2.5	0 ~ 25			●	

★ notice

- PS1M and PS2M series would be attached with the particular wrench.
- The thread and bushing parts are both in high precision and able to inhibit shaking.
- Thread part material : SUS303 ◦